




VITI A TESTA SVASATA 120° QUADRO SOTTO TESTA DX PASSO GROSSO



d	M10	M12	14	16
passo	1,5	1,75	2	2
D	19	20	23	26
c	7	7	10	10
b	20	20	30	34
lato quadro	10	12	14	16

