

VITI SENZA TESTA CON ESAGONO INCASSATO ED ESTREMITA' CONICA PASSO GROSSO



d		M3	M4	M5	M6	M8	M10	M12	M14	M16	M20
passo		0,5	0,7	0,8	1	1,25	1,5	1,75	2	2	2,5
S		1,5	2	2,5	3	4	5	6	6	8	10
t min. ^	A	1,2	1,5	2	2	3	4	4,8	5,6	6,4	8
	B	2	2,5	3	3,5	5	6	8	9	10	12

