


DADI ESAGONALI BASSI PASSO GROSSO



D	Passo	s	m
M4	0,7	7	2,4
M5	0,8	8	3
M6	1	10	4
M8	1,25	13	5
M10	1,5	17	6
M12	1,75	19	7
M14	2	22	8
M16	2	24	8
M18	2,5	27	9
M20	2,5	30	9
M22	2,5	32	10
M24	3	36	10
M27	3	41	12
M30	3,5	46	12