




DADI ESAGONALI ALTI PASSO GROSSO



D	Passo	s nomin.	m nomin.
M3	0,5	5,5	3
M4	0,7	7	4
M5	0,8	8	5
M6	1	10	6
M7	1	11	7
M8	1,25	13	8
M10	1,5	17	10
M12	1,75	19	12
M14	2	22	14
M16	2	24	16
M18	2,5	27	18
M20	2,5	30	20
M22	2,5	32	22
M24	3	36	24
M27	3	41	27
M30	3,5	46	30
M33	3,5	50	33
M36	4	55	36
M39	4	60	39
M42	4,5	65	42
M45	4,5	70	45
M48	5	75	48
M52	5	80	52
M56	5,5	85	56
M60	5,5	90	60
M64	6	95	64
M68	6	100	68
M72	6	105	72
M76	6	110	76
M80	6	115	80
M90	6	130	90
M100	6	145	100